

FIGURE 7: POTENTIAL IDENTIFIED SAFETY ISSUES

DISTRICT OF  
SQUAMISH

HIGHWAY 99


BLACKTUSK WAY

GARIBALDI WAY

DIAMOND HEAD  
ROAD

TANTALUS ROAD

TANTALUS ROAD



**T** No access from Hwy 99 to Tantalus Road heading south from Brackendale causes traffic congestion

**T** Vehicle speeding, particularly by Hwy 99 traffic

**A** High access density within a short distance

**A** Drivers going around the turning vehicles and use Garibaldi Way as a 4-lane road w/o left-turn bay

**P** Jaywalking reported between north and south sides of Garibaldi Way due to lack of crossing facility

**C** Discontinuity of the bike lane along Tantalus Road

**G** Drivers need to pull up further than the stop bar due to visibility issues

**A** Immediate left-turn to the gas station

**A** Proximity of the driveway to Tantalus Road southbound approach may cause confusion for left-turn vehicles

Long delay for left-turn vehicles **T**

Misaligned north and south legs at the intersection **G**

Southbound left-turn drivers from Tantalus Road not attentive of crossing pedestrians **P**

Driver's noncompliance to stop or pedestrians not using the push buttons **P**

Route #1  
Route #4  
Route #9

Route #1  
Route #9

Eastbound buses waiting at the near-side stop obstruct visibility to the special crosswalk **B**

Two eastbound bus stops within a short distance **B**

Route #1  
Route #2  
Route #4  
Route #9

Long delay for left-turn vehicles **T**

Condensed parking along Tantalus Road, and illegal parking due to overflow making visibility and access dangerous for pedestrians **P**

Backed up traffic at Hwy 99 intersection making turns onto Garibaldi Way difficult from accesses **T**

**G** Visibility issues when exiting onto Garibaldi Way

**A** Long delays/queues for vehicles exiting the Plaza parking lot

**A** Some drivers exiting the Plaza parking lot from south due to congested accesses onto Garibaldi Way

PLAZA  
PARKING  
ACCESS

Impatient drivers going through Chevron gas station to avoid long delay/queue **A**

Lack of sidewalk along both sides of the Plaza access **P**

ISSUE CATEGORY	
<b>T</b>	TRAFFIC OPERATION
<b>A</b>	ACCESS MANAGEMENT
<b>G</b>	GEOMETRIC
<b>P</b>	PEDESTRIAN
<b>C</b>	CYCLIST
<b>B</b>	BUS